



NOTES:

1. FOR ALL 1" SERVICES USE JONES J979 DOUBLE STRAP SADDLE WITH CORPORATION STOP (CC) THREAD.
2. FOR ALL 2" SERVICES USE JONES J979 DOUBLE STRAP SADDLE WITH IRON PIPE THREAD.
3. CORPORATION STOP SHALL BE INSTALLED ON THE MAIN DIRECTLY OPPOSITE THE LOCATION OF THE METER.
4. MINIMUM DISTANCE BETWEEN TAPS OR CONNECTIONS SHALL BE 18 INCHES, AND A MINIMUM OF 18 INCHES FROM END OF PIPE.
(FOR DIST. BETWEEN SERVICE TAPS CHECK METER BOX DIMENSIONS ON STD. T703 OR T704.)
5. FOR STEEL MAINS DELETE SERVICE SADDLE. A TAP NOZZLE SHALL BE WELDED TO MAIN AND AN INSULATING BUSHING SHALL BE INSTALLED BETWEEN THE TAP NOZZLE AND THE CORPORATION STOP.

ACCOMPANYING STD.'S T700 AND T703 OR T704.

CITY OF TORRANCE - ENGINEERING DEPARTMENT

**1" & 2" SERVICE
CONNECTION TO MAIN LINE**

STANDARD NO.

T702-1

SHEET 1 OF 1

DATE ISSUED
16 NOV 1998

RICHARD W. BURTT
ENGINEERING DIRECTOR
R.C.E. NO. 32862